

Old North Road, Weston
Newark, Notts. NG23 6SY
Telephone:
Service:- (01636) 821648
Parts:- (01636) 822144
Fax:- (01636) 821354

Hutchinson

Engineering Services Limited

www.hutchinson-uk.com
Email: info@hutchinson.uk.com

Ingram Lane Works
Sutton-on-Trent
Newark, Notts.
NG23 6RA

Tel: (01636) 821640
Fax: (01636) 821400

Report of thorough examination of Lifting Equipment

As required by The Lifting Operations & Lifting Equipment Regulations 1998 (Regulation 9 Section 3a II)

Name: *Maplebeck tree care*

Address: *Clay barn maplebeck NG22 0BS*

Item No & description	Report of examination Including defects affecting the safe working load and steps required to remedy such defects	Safe working load	Inspection frequency code
<i>Dmm Shackles</i>	<i>YR.</i>		
<i>L/safe Karabiner</i>	<i>K1 Good Condition 2014</i>	<i>1 Person</i>	<i>A</i>
	<i>K2 Good Condition 2014</i>	<i>1 person</i>	<i>A</i>
	<i>K3 Good Condition 2014</i>	<i>1 person</i>	<i>A</i>
	<i>K4 Good Condition 2014</i>	<i>1 person</i>	<i>A</i>
	<i>K5 Good Condition 2016</i>	<i>1 person</i>	<i>A</i>
<i>Skylotec Kolibri Harness</i>	<i>2D. H1 Good Condition 2014</i>	<i>1 person</i>	<i>A</i>
<i>Linos Iguile 12.8mm rope.</i>	<i>R1 Good Condition 2015</i>	<i>1 Person</i>	<i>A</i>
<i>Location</i>			
<i>H13 Flip line w/snaplock 3m</i>	<i>L1 Good Condition 2016</i>	<i>1 Person</i>	<i>A</i>
<i>Distel Aluminium Spurs</i>	<i>S1 Good Condition 2014</i>	<i>1 person</i>	<i>A</i>
<i>H13 Flip line w/snaplock 3m</i>	<i>F1 Good Condition 2014</i>	<i>1 Person</i>	<i>A</i>
<i>Dmm Friction Pulley</i>	<i>FRI Good Condition 2017</i>	<i>1 Person</i>	<i>A.</i>

Code A.	Last Inspection	This Inspection	Next Inspection
		<i>26-6-2017</i>	<i>26-12-2017</i>
Code B.	Last Inspection	This Inspection	Next Inspection
Signed	<i>P Fost</i>	Engineer / Surveyor	Date <i>26-6-2017</i>

CODE A. 6 MONTHLY
CODE B. 12 MONTHLY